



Installation Requirement of AHL-YAG-50W

Installation Requirement of AHL-YAG-50W:

1. Interspace requirement
2. Electrical source requirement
3. Preparation before installation
4. Installation sketch chart








Equipment Photo:



Equipment List for AHL-YAG-50W

Equipment List

No	Outline size	Q'ty	Main parts
1. Laser		1 set	.resonance mirror 1 set
			.acousto-optic Q-switch 1 set
			.laser bar 1 set
			.red indicator 1 set
2. Power supply		1 set	.Power supply 1 set
			.Computer 1 set
			.Controlling system 1 set
			.Marking software 1 set
3. Chiller		1 set	.High efficiency compressor, temperature alert, flux protection, double circulation
4. Outer air-condition		1 set	. Cooling system, outer air-condition
5. Worktabl		1 set	. 3-D manual
6	monitor	1 set	. 17" CRT
7	Necessary accessories	1 set	. Power supply wire 2 pcs . Mouse / Keyboard 1 set . Insulating adhesive tape 1 roll . Tight hoop 10 pcs . Teflon tape 1 box
8	Other accessories	1 set	. Cleaning tissue 1 wrap . Metal name card 1 box . Frequency doubling patch 1 pc . Software CD 1 set . Filter core 1 pc . Qualified certification 1pc . User guide 1pc